

August 7, 2023

VIA ELECTRONIC MAIL

Mr. Michael Terpinski
Ohio EPA, NWDO, DERR
347 North Dunbridge Road
Bowling Green, OH 43402

**Re: EnviroSAFE Services of Ohio, Inc.
EPA Identification Number: OHD 045 243 706
July 2023 Progress Report**

Dear Mr. Terpinski:

In accordance with Condition E.13 of its Ohio Hazardous Waste Facility Installation and Operation Permit (the "Permit"), EnviroSAFE Services of Ohio, Inc. ("ESOI") hereby submits this progress report to the Ohio Environmental Protection Agency ("Ohio EPA") for the period beginning July 1, 2023 and ending July 31, 2023.

Corrective Measures Implementation ("CMI"):

Project Activities:

During this reporting period, CMI activities included the following:

1. Yield testing of the leachate extraction system was initiated and will continue through next month;
2. Leachate system maintenance included:
 - Inspection of piezometers and recovery wells on SWMUs 5, 6, and 7:
 - Recorded liquid level at each location with a control panel;
 - Verified functionality of all pumps without a control panel;
 - RW-2: Adjusted pumping interval, returned original pump/tubing/cable for RW-2 (previously removed for use in NRP-29);
 - DPW-19: Found above hi point – turned off and back on; pumped down and began cycling;
 - PZ-13: Installed new timer for controller;
 - PZ-15: Installed new timer for controller;
 - DPW-21R: Found above hi point – suspected pump issue – scheduled for repair (levels typically very stable and pumping not required);
 - NRP-29: Repaired slight leak at force main; replaced pump/tubing/cable with same from RW-7 (not part of current network) and installed to approximate same depth;
 - NRP-35: Found above hi point – turned off and back on; pumped down and began cycling;

Mr. Michael Terpinski

August 7, 2023

Page 2

- SWMU 5 Tank Containment: Run sump pump to remove water;
 - SWMU 5 Compressor: Drained moisture from controller;
 - SWMU 6 Compressor: Emptied buckets, compressor attic fan was observed to be functioning as designed; and
3. Solar Sipper – inspected and found to be operating slowly. The display periodically shuts down – suspected power issue.

Summary of All CMI-Related Contacts with the Public:

ESOI has not had any related contacts with the public during this reporting period.

Summary of Potential or Encountered Problems and Rectification Actions:

There is nothing to report in association with this topic for this reporting period.

Projected Work:


During the next reporting period it is anticipated that the following activities will occur:

1. Evaluate and repair solar sipper power issue;
2. Complete remaining yield tests for active leachate recovery wells;
3. Dispose collected NAPL from Solar Sipper; and
4. Continued operation and maintenance of the leachate extraction systems on SWMUs 5, 6, and 7.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

If you have any questions, please do not hesitate to contact Stephen DeLussa at (215) 659-2001 ext. 15.

Sincerely,



Douglas E. Roberts
President

cc: Gary Deutschman, Ohio EPA-NWDO, DERR
Stephen DeLussa, Envirosource Technologies, Inc.
Michael Momenee, The Mannik & Smith Group

Dawn Pleiman, Ohio EPA-NWDO, DERR
Mark Nielsen, Ramboll