



876 Otter Creek Road
Oregon, Ohio 43616-3518
Phone: (419) 698-3500
Fax (419) 698-8663
Website: www.envirosafeservices.com

November 12, 2021

VIA ELECTRONIC MAIL

Ms. Colleen Weaver
Ohio EPA, NWDO, DERR
347 North Dunbridge Road
Bowling Green, OH 43402

**Re: Envirosafe Services of Ohio, Inc.
 EPA Identification Number: OHD 045 243 706
 October 2021 Progress Report**

Dear Ms. Weaver:

In accordance with Condition E.13 of its Ohio Hazardous Waste Facility Installation and Operation Permit (the "Permit"), Envirosafe Services of Ohio, Inc. ("ESOI") hereby submits this progress report to the Ohio Environmental Protection Agency ("Ohio EPA") for the period beginning October 1, 2021 and ending October 31, 2021.

Corrective Measures Implementation ("CMI"):

Project Activities:

During this reporting period, CMI activities included the following:

1. Storm water drainage planning for SWMU 8 (Old Oil Pond);
2. Discussion with Ohio EPA regarding changes and 30-day extension of the review period for the permit modification submitted on September 7, 2021 regarding Ohio EPA's recommendations for winter weather shutdown of the leachate systems for SWMUs 5, 6, and 7;
3. Finalized well specifications for SWMU 8;
4. Reviewed and commented on draft renewal POTW Discharge Order from the City of Toledo Department of Environmental Services;
5. Collection of semi-annual leachate system elevation measurements on October 28-29, 2021. An inward gradient continues to be maintained and demonstrate achievement of the performance standard: maintenance of the leachate head level measurement below a gradient based TLL of 3.0 feet below the lowest groundwater elevation in the relevant shallow perimeter monitoring well(s);
6. Leachate system maintenance included:
 - Inspection of piezometers and recovery wells on SWMUs 5, 6, and 7:
 - Recorded liquid level at each location with a control panel;
 - Verified functionality of all pumps without a control panel;

- All pumps with a control panel were observed to be below their respective low points with the exception of: DPW-18, NRP-24, 25, 26, 27, 29, 30, 31, 33, 34, and 35;
- NRP-27: Observed above the Hi Point. Removed obstruction in globe valve, flushed valve train, cleaned pump, replaced transducer – pumped down and began cycling normally
- SWMU 5 Compressor: drained moisture from controller; and
- SWMU 6 Compressor: Emptied buckets, compressor attic fan was observed to be functioning as designed; and

7. Solar Sipper – inspected and found to be operating as designed.

Summary of All CMI-Related Contacts with the Public:

ESOI has not had any related contacts with the public during this reporting period.

Summary of Potential or Encountered Problems and Rectification Actions:

There is nothing to report in association with this topic for this reporting period.

Projected Work:


During the next reporting period it is anticipated that the following activities will occur:

1. Install storm water drainage structure of SWMU 8 (Old Oil Pond) and seeding;
2. Initiating the well installation project for SWMU 8 pending contractor availability;
3. Reseed areas where necessary on SWMU 9 (New Oil Pond);
4. SWMU 6 property line excavation for waste removal; and
5. Continued operation and maintenance of the leachate extraction systems on SWMUs 5, 6, and 7.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

If you have any questions, please do not hesitate to contact Stephen DeLussa at (215) 659-2001 ext. 15.

Sincerely,



Douglas E. Roberts
President

ec: Michael Terpinski, Ohio EPA-NWDO, DERR
Stephen DeLussa, Envirosource Technologies, Inc.
Mark Nielsen, Ramboll

Dawn Pleiman, Ohio EPA-NWDO, DERR
Gary Deutschman, Ohio EPA-NWDO, DERR
Michael Momenee, The Mannik & Smith Group